



ISO 9001, ISO 14001

User manual and maintenance instruction for the dispenser WOPA

Dispensers WOPA are especially intended or dosing of liquid abrasive soaps.

Installation:

- 1. Using the attached key, open the front cover of the dispenser and take out the tank with dosing pump.
- 2. Fix the dispenser to the wall with attached 4 screws, minimally 10 cm above the washbasin.
- 3. Return the tank back to the dispenser.
- 4. Fill in the abrasive soap isofa through the upper gap and close with a cap.
- 5. Fill in just only original suspensions isofa, do not dilute the content.
- 6. Close the front cover of the dispenser until it clicks, and push the button a few times to the maximal position to push out the air and fill the pump with soap.
- 7. During this, the dispenser can sputter. Cover the pump with your hand to avoid pollution of surrounding.
- 8. Ready dispenser doses 1,5 ml of the soap and does not sputter.

The full dose is 1,5 ml of abrasive soap, what is suitable amount for washing of ordinarilly polluted hands.

For higher level of pollution use 2 - 3 doses or repeat washing itselves

Do not forget to refill the tank of dispenser in-time to avoid air coming into the pump. During ordinary refilling it is not necessary to take out the tank.

Cleaning and maintenance:

1. In case of in-time refilling the dispenser does not need any special maintenance. Wash the dispenser once a year.

- 2. Wash the dispenser always when you change the kind of soap or when the dispenser is blocked.
- 3. Screw out the pump from the tank of the dispenser and take out the part with membrane valve.
- 4. Push out the rest of suspensions (soap) and rinse with water.







Office: Průmyslová 1420 Bystřice nad Pernštejnem 593 01

IČ: 255 47 593 DIČ: CZ 255 47 593 banka: 27-3946650227 / 0100

tel: +420 565 400 300 fax: +420 566 551 822 e-mail: info@cormen.cz www:cormen.cz